

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**Q109** **NEPTUNE AUTO REPAIR**  
**WSW** **1418 NEPTUNE AVENUE**  
**1/8-1/4** **BROOKLYN, NY 11224**

**0.202 mi.**  
**1067 ft.**

**Site 1 of 2 in cluster Q**

**NY AST** **A100295228**  
**N/A**

**Relative:**  
**Higher**

**AST:**

**Actual:**  
**2 ft.**

Name: NEPTUNE AUTO REPAIR  
Address: 1418 NEPTUNE AVENUE  
City,State,Zip: BROOKLYN, NY 11224  
Region: STATE  
DEC Region: 2  
Site Status: Active  
Facility Id: 2-609919  
Program Type: PBS  
UTM X: 586109.58164  
UTM Y: 4492522.12843  
Expiration Date: 04/14/2010  
Site Type: Other

**Affiliation Records:**

Site Id: 343627  
Affiliation Type: Facility Owner  
Company Name: SHMULENZON VLADIMIR  
Contact Type: PRESIDENT  
Contact Name: VLADIMIR SHMULENZON  
Address1: 3145 BRIGHTON 4ST #212  
Address2: Not reported  
City: BROOKLYN  
State: NY  
Zip Code: 11235  
Country Code: 001  
Phone: (718) 714-4157  
EMail: Not reported  
Fax Number: Not reported  
Modified By: MABARTLE  
Date Last Modified: 2005-04-14

Site Id: 343627  
Affiliation Type: Mail Contact  
Company Name: NEPTUNE AUTO REPAIR  
Contact Type: Not reported  
Contact Name: VLADIMIR SHMULENZON  
Address1: 1418 NEPTUNE AVENUE  
Address2: Not reported  
City: BROOKLYN  
State: NY  
Zip Code: 11224  
Country Code: 001  
Phone: (718) 714-4157  
EMail: Not reported  
Fax Number: Not reported  
Modified By: MABARTLE  
Date Last Modified: 2005-04-14

Site Id: 343627  
Affiliation Type: Facility Operator  
Company Name: NEPTUNE AUTO REPAIR  
Contact Type: Not reported  
Contact Name: SHMULENZON VLADIMIR

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Address1: Not reported  
Address2: Not reported  
City: Not reported  
State: NN  
Zip Code: Not reported  
Country Code: 001  
Phone: (718) 714-4157  
EMail: Not reported  
Fax Number: Not reported  
Modified By: MABARTLE  
Date Last Modified: 2005-04-14

Site Id: 343627  
Affiliation Type: Emergency Contact  
Company Name: SHMULENZON VLADIMIR  
Contact Type: Not reported  
Contact Name: SHMULENZON SIMA  
Address1: Not reported  
Address2: Not reported  
City: Not reported  
State: NN  
Zip Code: Not reported  
Country Code: 999  
Phone: (718) 332-2145  
EMail: Not reported  
Fax Number: Not reported  
Modified By: NRLOMBAR  
Date Last Modified: 2005-04-14

Tank Info:

Tank Number: 1  
Tank Id: 196592  
Material Code: 0022  
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

A00 - Tank Internal Protection - None  
B01 - Tank External Protection - Painted/Asphalt Coating  
I01 - Overfill - Float Vent Valve  
E00 - Piping Secondary Containment - None  
H00 - Tank Leak Detection - None  
  
K01 - Spill Prevention - Catch Basin  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
D00 - Pipe Type - No Piping  
L00 - Piping Leak Detection - None  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.  
Tank Type: Steel/Carbon Steel/Iron  
Tank Status: In Service  
Pipe Model: Not reported  
Install Date: 01/01/2005  
Capacity Gallons: 300  
Tightness Test Method: NN  
Date Test: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MABARTLE
Last Modified:	04/14/2017
Material Name:	waste oil/used oil